

### **AMENDMENTS TO THE FIGURES**

A replacement sheet is submitted replacing Figure 2 with amended Figure 2. Amended Figure 2 removes one of the characters "9" as well as shows the thickness of the guide bushing 24' completely surrounding the bearing tube.